Roanoke County Schools

Three Year AHERA Reinspection

Masons Cove Elementary School Facility 022

Reinspection Date: February 1, 2008

Baratta & Associates, Inc PO Box 293 Vinton, Virginia 24179 540-890-4875

Michael Baratta, PE

Virginia Asbestos Inspector License: 3303-000065

Virginia Asbestos Management Planner License: 3304-000208

Baratta & Associates, Inc.

Virginia Department of Education Energy and Facilities Service LEA Roanoke County Schools
School Masons Cove Elementary School
Building Main

SCHOOL BUILDINGS

Building Name Location		Check here for the presence of:			No ACBM	
		AC	BM		pect BM	
		Friable	Non- friable	Friable	Non- friable	
Masons Cove Elementary School	3370 Bradshaw Road Salem, VA 24153	X				

	11/11/2	
Inspector:	1/1/1/1/2- 2 2 2 2 2 2 2	
Name: Michael Baratta	Signature Date 2-13-09	
Accreditation Number: 220	02 000065 Agency: Virginia DDOP	

Virginia Department of Education Energy and Facilities Services LEA Roanoke County Schools
School: 022 Masons Cove Elementary School
Building: Main

DETERMINATION OF EACH SAMPLE AREA

Floor Tile 06 may have been replaced. We sampled 06A (tile) and 06B (mastic) where HA-06 was reported to exist. In addition, new homogeneous areas for the wall bases and associated mastics (015, 016, 017 & 018) were established. Two (2) samples of each were obtained.


Homogeneous Area	Material	Sample Number	Location
06A	Floor tile 12"x12", light	06A-1	127A, SE corner
	grey with white & grey streaks	06A-2	Hall at corner of 124
06B	Black mastic for HA-06A	06B-1	127A, SE corner
		06B-2	Hall at corner of 124
015	Wall base 4", black, at floor	015-1	127A, SE corner
	tiled areas	015-2	Hall at corner of 124
016	Tan mastic for HA-015	016-1	127A, SE corner
		016-2	Hall at corner of 124
017	Wall base 4", black, at	017-1	Hall at 131
	terrazzo areas	017-2	Hall at 110
018	Tan mastic for HA-017	018-1	Hall at 131
		018-2	Hall at 110

Name: Michael Baratta

Signature

Date_ 2 -13-08

Accreditation Number: 3303 000065 Agency: Virginia DPOR



Document E.1

Virginia Department of Education Energy and Facilities Services

BULK SAMPLE ANALYSIS

LEA Roanoke County Schools
School: 022 Masons Cove Elementary School

Building: Main

Sample Date: February 1, 2008

Analysis Date: February 6, 2008

Analysis Method: PLM EPA 6000/M4-82-020

Homogeneous Area	Sample Number	Material	Asbestos Content
06A	06A-1	Floor tile 12"x12", light grey with white	NAD
	06A-2	& grey streaks	NAD
06B	06B-1	Black mastic for HA-06A	NAD
	06B-2		NAD
015	015-1	Wall base 4", black, at floor tiled areas	NAD
	015-2		NAD
016	016-1	Tan mastic for HA-015	NAD
	016-2		NAD
017	017-1	Wall base 4", black, at terrazzo areas	NAD
	017-2		NAD
018	018-1	Tan mastic for HA-017	NAD
	018-2		NAD

NAD - no asbestos detected

See attached Ameri	Sci PLM Bulk A	Asbestos Report Number 108021179
		1/1/1/0-11
Name: Michael Baratta	Signature	Date 2/13/00
Accreditation Number: 330)3 000065 Ager	111



AmeriSci Richmond

13635 GENITO ROAD MIDLOTHIAN, VIRGINIA 23112 TEL: (804) 763-1200 • FAX: (804) 763-1800

PLM Bulk Asbestos Report

Baratta & Associates, Inc. Attn: Michael Baratta 1150 Shady Run Road

Date Received

02/06/08

AmeriSci Job #

108021179

Date Examined 02/06/08

P.O. # Page

3 of

RE: L001; Masons Cove E/S; Ahera

Vinton, VA 24179

Client No. / H	/ HGA Lab No. Asbestos Present		Asbestos Present	Total % Asbestos	
06A-1 Location: Floor Tile		108021179-01	No	NAD (by CVES) by David W. Ralbovsky on 02/06/08	
Asbestos	l ption: Beige/Tan, Heteroge Types: aterial: Non-fibrous 100 %	neous, Non-Fibrous, Bu	lk Material		
06A-2	Location: Floor Tile	108021179-02	No	NAD (by CVES) by David W. Ralbovsky on 02/06/08	
Asbestos	iption: Beige/Tan, Heterogei Types: aterial: Non-fibrous 100 %	neous, Non-Fibrous, Bu	ik Material		
06B-1	Location: Floor Tile Mas	108021179-03 stic	No	NAD (by CVES) by David W. Ralbovsky on 02/06/08	
Asbestos	iption: Black, Heterogeneou Types: iterial: Cellulose 5 %, Non-f	3	aterial <u>i</u> j		
06B-2	Location: Floor Tile Mas	108021179-04 stic	No	NAD (by CVES) by David W. Ralbovsky on 02/06/08	
Asbestos	l ption: Black, Heterogeneou 「ypes: It erial: Cellulose 3 %, Non-f		aterial	-	
015-1	Location: Base at Floor	108021179-05 Tile	No	NAD (by CVES) by David W. Ralbovsky on 02/06/08	
Asbestos	ption: Black, Heterogeneou Types: terial: Non-fibrous 100 %	s, Non-Fibrous, Bulk Ma	aterial		

AmeriSci Job #: 108021179

Client Name: Baratta & Associates, Inc.

PLM Bulk Asbestos Report

L001; Masons Cove E/S; Ahera

Client No. / F	IGA Lab N	o. Asbestos Present	Total % Asbestos
015-2	108021179 Location: Base at Floor Tile		NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos	ription: Black, Heterogeneous, Non-Fibrou Types: laterial: Non-fibrous 100 %	s, Bulk Material	
016-1	108021179 Location: Base Mastic	9-07 No	NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos	ription: Belge, Heterogeneous, Non-Fibrou Types: aterial: Cellulose Trace, Non-fibrous 100 %		
016-2	108021179 Location: Base Mastic		NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos	ription: Beige, Heterogeneous, Non-Fibrou Types: aterial: Cellulose 2 %, Non-fibrous 98 %	s, Bulk Material	
017-1	108021179 Location: Base	9-09 No	NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos	i ptlon : Black, Heterogeneous, Non-Fibrous T ypes: aterlal: Non-fibrous 100 %	s, Bulk Material	
017-2	108021179 Location: Base	9-10 No	NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos '	iption: Black, Heterogeneous, Non-Fibrous Types: I terial: Non-fibrous 100 %	s, Bulk Material	
)18-1	108021179 Location: Base Mastic	-11 No	NAD (by CVES) by David W. Ralbovsky on 02/06/08
Asbestos 1	ption: Beige, Heterogeneous, Non-Fibrous Fypes: terlal: Cellulose Trace, Non-fibrous 100 %		

AmeriSci Job #: 108021179

Asbestos Types:

Other Material: Non-fibrous 100 %

Client Name: Baratta & Associates, Inc.

PLM Bulk Asbestos Report

L001; Masons Cove E/S; Ahera

Lab No.	Asbestos Present	Total % Asbestos
108021179-12	No	NAD
astic		(by CVES) by David W. Ralbovsky on 02/06/08
	108021179-12	108021179-12 No

Reporting Notes:

Analyzed by: David W. Ralbovsky

"NAD = no asbestos detected, Detection Limit <120, Reporting Limits: CVES = 1%, 490 Pt. it = 0.25%, 1000 Pt Ct = 0.1%; "Present" or NVA = "No Visible Asbestos" are observations made during a qualifative analysis; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 101904-0) and ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples)(NYSDOH ELAP Lab # 10984); CA ELAP Lab # 2508; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the Items tested.

Reviewed By:

Baratta & Associates, Inc.

P.O. Box 293 Vinton, Virginia

18

LEA	Roanoke County Schools
School	022 Masons Cove Elementary School
Building	Main

Not evaluated

Non-ACM

REASSESSMENT OF MATERIALS

Past or Initial Assessment: Hall-Kimbrell April 1989

The TSI (HA-11) on Boiler Number 1 removed and TSI on Boiler Number 2 repaired on February 1, 2008.

	ining surface ceiling plaster (HA-07) is enclosed with a g		
Homogeneous	Description	Past	Reassessment
Area		Assessment	Category #
		Category #	
02	Pipe run TSI domestic HW in tunnels	1	1
03	Fitting TSI domestic HW in tunnels	1	1
04	Fitting TSI domestic HW in Tunnels	1	1
05	Fitting TSI domestic CW in tunnels	1	1
06A	Floor tile 12"x12", light grey with white & grey streaks	Non-ACM	Non-ACM
06B	Black mastic for HA-06A	Not evaluated	Non-ACM
07	Surfacing ceiling plaster (see note above)	3	2
08	Ceiling LIC or ACT	Non-ACM	Non-ACM
09	Ceiling LIC or ACT	Non-ACM	Non-ACM
10	Ceiling LIC or ACT	Non-ACM	Non-ACM
11	Boiler TSI (see note above)	1	6
12	Fitting Muds in Boiler Room	1	1
13	Pipe run TSI in Boiler Room	1	1
14	Tank TSI in Boiler Room	1	1
15	Wall base 4", black at floor tiles	Not evaluated	Non-ACM
16	Tan mastic for HA-15	Not evaluated	Non-ACM
17	Wall base 4", black at terrazzo floors	Not evaluated	Non-ACM

AHERA - Physical Assessment Categories - 763.88(a)(2)(b)	AHERA -	Physical Assessment	Categories -	763.88(a)(2)(b)
--	---------	---------------------	--------------	-----------------

1 Damaged or significantly damaged TSI-ACBM

Tan mastic for HA-17

- 2 Damaged friable surfacing ACBM
- 3 Significantly damaged friable surfacing ACBM
- 4 Damaged or significantly damaged friable miscellaneous ACBM
- 5 ACBM with potential for damage
- 6 ACBM with potential for significant damage
- 7 Any remaining friable ACBM or friable suspect ACBM

J		11/12	//			
Inspector:		////	10	/	6- /	
Name: Michael Baratta	Signature		Date_	2/	83/	06
Accreditation Number: 330	3 000065 Ag	ency: Virginia D	POR			

Document G

Virginia Department of Education Energy and Facilities Service

School Masons Cove		_
	Elementary School	-
Building:		_
Total cost to remove	\$250,000	

RESPONSE ACTIONS RECOMMENDED

Each Location	Recommended Response Actions	Scheduled To Begin	Scheduled To Be Completed	Est. Cost To Remove
TSI in Tunnels	Restrict tunnel access until TSI can be removed	none	none	\$20,000
TSI in Boiler Room (Boiler Number 2, Tanks and Piping Systems)	Repair damaged TSI. Place in O & M plan until other needs require the TSI be removed	none	none	\$30,000
Surface Ceiling Material	Monitor for any future damage. Place in O & M plan until other needs require the ceiling to be removed	none	none	\$200,000

Management Planner:			1/1/1			
Name: Michael Baratta	Signature_	/////	10	Date_	2-13-69	
Accreditation Number: 33	04 000208	Agency: Virgi	nia DPOP			

LOCATION OF ACBMs

Floor Plan

ASBESTOS MANAGEMENT, OPERATIONS AND MAINTENANCE PLAN

Masons Cove Elementary School February 13, 2008

This Asbestos Management Operations and Maintenance Plan is based on the three (3) year AHERA Reinspection performed by Baratta & Associates, Inc on February 1, 2008. It covers procedures to be followed in dealing with the Asbestos-Containing Materials (ACMs) found in the Masons Cove Elementary School

SUMMARY

Most of the thermal system insulations (TSIs) in the Boiler Room and in part of the tunnels are ACMs. A few damaged areas were noted. We recommend the damaged areas be repaired. The asbestos containing TSI on Boiler Number 1 was removed in February 2008.

Asbestos containing acoustical plaster was once exposed in the halls and some of the rooms. The School System covered this plaster with a gypsumboard enclosure. This protects it from damage.

STAFF NOTIFICATION

The School should send all staff members a brief notice stating that Asbestos-Containing Materials exist in the Masons Cove School Building.

ACM IDENTIFICATION

The following products were found to be Asbestos-Containing Materials (ACMs):

HA Number	Material	Location	
02	Domestic HW pipe run TSI	Tunnels	
03	Domestic HW fitting TSI	Tunnels	
04	Domestic HW fitting TSI (fiberglass pipe runs)	Tunnels	
05	Domestic CW fitting TSI	Tunnels	
07	Ceiling plaster	Halls and Some Rooms	
011	Boiler TSI	Boiler Room	
012	Pipe fitting TSI	Boiler Room	
013	Pipe fitting TSI	Boiler Room	
014	Tank TSI	Boiler Room	

CARE OF THE ASBESTOS CONTAINING CEILING PLASTER

This material is found in some of the halls and rooms. It was enclosed behind a gypsumboard enclosure thus protecting it from physical damage. In its current condition, it does not present an asbestos related health hazard to the building occupants.

Do not drill into or hang any objects from the ceiling.

If you notice the ceiling is water stained or shows other signs of damage please report it to the principal so appropriate actions can be taken.

CARE OF THE THERMAL SYSTEM INSULATION (TSI) IN TUNNELS

These tunnels are under the floor. The ACMs in the tunnels do not present an asbestos related health hazard to those occupying the main floor.

The tunnels should be sealed off to prevent entry by unauthorized personnel. An asbestos warning label should be applied to the tunnel entrance in the Boiler Room as well.

CARE OF THE THERMAL SYSTEM INSULATION (TSI) IN BOILER ROOM

The damaged TSI in the Boiler Room should be repaired. Once the damaged areas are repaired, asbestos warning signs should be applied to all doors leading to the Boiler Room.

Custodial and maintenance personnel should take care not to damage or disturb the TSI while performed their duties. Any damaged areas should be reported to the Principal so repairs can be made.

Any patching, repair work or removal should be carried out by a licensed asbestos abatement contractor.

PERMIT REQUIREMENTS

Before any work that may require the disturbance of the noted Asbestos Containing Materials is performed, maintenance personnel or contractors shall obtain an Asbestos Work Area Permit from the School System's Asbestos Program Manager.