Roanoke County Schools

Three Year AHERA Reinspection

William Byrd Middle School Facility 038

Reinspection Date: February 19, 2008

Baratta & Associates, Inc PO Box 293 Vinton, Virginia 24179 540-890-4875

Michael Baratta, PE

Virginia Asbestos Inspector License: 3303-000065

Virginia Asbestos Management Planner License: 3304-000208

Baratta & Associates, Inc.

Virginia Department of Education Energy and Facilities Service LEA Roanoke County Schools
School 038 William Byrd Middle School
Building Main

SCHOOL BUILDINGS

Building Name	Location	Location Check here for the presence of:		nce of:	No ACBM	
		AC	ВМ	1	pect BM	
		Friable	Non- friable	Friable	Non- friable	
038 William Byrd Middle School	2910 Washington Avenue Vinton, VA 24179					X

Note: This is a new school building. The William Byrd Middle School evaluated by Hall Kimbrell in 1988 is now the Central Middle School, Facility Number 009

	11/2/6 0			
Inspector:			11 1	
Name: Michael Baratta Signa	ture_////	Date	9/10/08	
Accreditation Number: 3303 00006	5 Agency: Virginia DPOR		1.1.0	

Virginia Department of Education Energy and Facilities Services


LEA	Roanoke County Schools
School:	038 William Byrd Middle School
Building:	Main

DETERMINATION OF EACH SAMPLE AREA

William Byrd Middle School was built in 1988. We assumed that no ACMs were used in its construction. Fiberglass TSI was observed through-out the building and in the mechanical spaces. We obtained several samples of the lay-in ceiling panels (LICs) as they were the most friable potentially suspect materials observed.

Homogeneous Area	Material	Sample Number	Location
01	LIC 2' x 2', random	01A	210, NE corner
	pattern	01B	122, center of room

Name: Michael Baratta Signature Date 4/0/06
Accreditation Number: 3303 000065 Agency: Virginia DPOR



Baratta & Associates. Inc. P.O. Box 293 Vinton. VA 24179

Baratta & Associates, Inc. P.O. Box 293 Vinton, VA

Document E.1

Virginia Department of Education Energy and Facilities Services

BULK SAMPLE ANALYSIS

LEA Roanoke County Schools

School: 038 William Byrd Middle School

Building: Main

Sample Date: February 12, 2008

Analysis Date: February 13, 2008

Analysis Method: PLM EPA 6000/M4-82-020

Homogeneous Area	Sample Number	Material	Asbestos Content
01	01A	LIC 2' x 2', random pattern	NAD
	01B	-	NAD

NAD - no asbestos detected

See attached AmeriSci PLM Bulk Asbestos Report Number 108021594

Name: Michael Baratta Signature Date 4/10/08
Accreditation Number: 3303 000065 Agency: Virginia DPOR



AmeriSci Richmond

13635 GENITO ROAD MIDLOTHIAN, VA 23112 TEL: (804) 763-1200 • FAX: (804) 763-1800

February 22, 2008

Baratta & Associates, Inc. Attn: Michael Baratta 1150 Shady Run Road Vinton, VA 24179

RE: Baratta & Associates, Inc. Job Number 108021594

P.O. #L001

L001; WB MS; Ahera

Dear Michael Baratta:

Enclosed are the results for PLM asbestos analysis of the following Baratta & Associates, Inc. samples received at AmeriSci on Thursday, February 21, 2008, for a 48 hour turnaround:

01A, 01B

The 2 samples contained in zip lock bag were shipped to AmeriSci via Hand Delivered. These samples were prepared and analyzed according to the EPA Interim Method (EPA 600/M4-82-020 per 40 CFR 763, subpt F, App. A). The required analytical information, analysis results, analyst signature and laboratory identification is contained in the Analyst's Report.

This report relates ONLY to the sample analysis expressed as percent asbestos. AmeriSci assumes no responsibility for customer supplied data such as "sample type", "location", or "area sampled". This report must not be used to claim product endorsement by AmeriSci, NVLAP or any agency of the U. S. Government. The National Institute of Standards and Technology Accreditation requirements, mandates that this report must not be reproduced, except in full without the written approval of the laboratory. This report may contain specific data not covered by NVI AP or FLAP accreditations respectively if AmeriSci appreciates this opportunity to serve your organization. Please contact us for any further assistance or with any questions.

Sincerely

T. Brian Keith

Asbestos Laboratory Director



AmeriSci Richmond

13635 GENITO ROAD MIDLOTHIAN, VIRGINIA 23112 TEL: (804) 763-1200 • FAX: (804) 763-1800

PLM Bulk Asbestos Report

Baratta & Associates, Inc.

Attn: Michael Baratta 1150 Shady Run Road **Date Received** 02/21/08

RE: L001; WB MS; Ahera

AmeriSci Job #

108021594

Date Examined 02/22/08

No

P.O. # Page

Vinton, VA 24179

Client No.	/ HGA	Lab No.	Asbestos Present	Total % Asbestos
01A		108021594-01	No	NAD
	Location: Lay	/- In-Ceiling		(by CVES)
				by David W. Ralbovsky
Analyst D	escription: White/Lt G	Grav Hataroganaous Eibrous Rui	Uc Matarial	on 02/22/08

st Description: White/Lt. Gray, Heterogeneous, Fibrous, Bulk Material

Asbestos Types:

Other Material: Cellulose 65 %, Fibrous glass 13 %, Non-fibrous 5 %, Perlite 17 %

01B 108021594-02 NAD

(by CVES)

by David W. Ralbovsky

on 02/22/08

Analyst Description: White/Lt. Gray, Heterogeneous, Fibrous, Bulk Material

Location: Lay- In-Ceiling

Asbestos Types:

Other Material: Cellulose 65 %, Fibrous glass 13 %, Non-fibrous 5 %, Perlite 17 %

Reporting Notes:

Analyzed by: David W. Ralbovsky *NAD = no asbestos detected, Detection limit <1% Reporting Limits: = 0.25%, 1000 Pt Ct = 0.1%; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Cote 101) 04-0) and ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples)(NYSDOH ELAP Lab # 10984); CA ELAP Lab # 2508; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if nis material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested Reviewed By:

Baratta & Associates, Inc.

P.O. Box 293 Vinton, Virginia

LEA	Roanoke County Schools
School	038 William Byrd Middle School
Building	Main

REASSESSMENT OF MATERIALS

Past or Initial Assessment: Not evaluated by Hall Kimbrell in 1988

Homogeneous Area	Description	Past Assessment Category #	Reassessment Category #
01	LIC 2' x 2', random pattern	Not evaluated	Non-ACM

AHERA - Physical	Assessment	Categories -	763.88(a)(2)(b)
------------------	------------	--------------	-----------------

- 1 Damaged or significantly damaged TSI-ACBM
- 2 Damaged friable surfacing ACBM
- 3 Significantly damaged friable surfacing ACBM
- 4 Damaged or significantly damaged friable miscellaneous ACBM
- 5 ACBM with potential for damage
- 6 ACBM with potential for significant damage
- 7 Any remaining friable ACBM or friable suspect ACBM

	10/1		
Inspector:	1/11/1/2	.,	///
Name: Michael Baratta Signature	111111	Date_ 9	1000
Accreditation Number: 3303 000065	Agency: Virginia DPOR		

Document G

Virginia Department of Education Energy and Facilities Service

LEA_ Roanoke Cour	nty Schools
School 034 William By	yrd Middle School
Building:	Main
Total cost to remove	\$0.00

RESPONSE ACTIONS RECOMMENDED

Each Location	Recommended Response Actions	Scheduled To Begin	Scheduled To Be Completed	Est. Cost To Remove
none				\$0.00

Management Planner:
Name: Michael Baratta Signature
Accreditation Number: 3304 000208 Agency: Virginia DPOR

ASBESTOS MANAGEMENT, OPERATIONS AND MAINTENANCE PLAN

038 William Byrd Middle School April 7, 2008

This Asbestos Management Operations and Maintenance Plan is based on the Three Year AHERA Reinspection performed by Baratta & Associates, Inc. on February 19, 2008. It covers procedures to be followed in dealing with the Asbestos-Containing Materials (ACMs) found in the William Byrd Middle School.

SUMMARY

William Byrd Middle School was built in 1988. We assumed no ACMs were used in its construction.

Non-suspect fiberglass thermal system insulation (TSI) was noted through-out the facility.

Samples from the more friable lay-in ceiling tiles (LICs) tested no asbestos detected.

RECOMMENDED ASBESTOS RELATED PROCEDURES

No asbestos related procedures are present at this time.

Should additional suspect materials be damaged or if they are questioned, we recommend they be sampled and tested for asbestos mineral content. The results of these tests will dictate what, if any, response actions are applicable.